



Photo 1 – First on scene photo, taken by search and rescue crews. Photo provided by Alaska State Troopers



Photo 2 - Photo of accident airplane's empennage.



Photo 3 - Photo of accident airplane's left side, cargo door area.



Photo 4 - Photo of accident airplane's severed right wing in foreground, and main wreckage in background.



Photo 5 -Photo of accident airplane's empennage and aft fuselage. Photo taken from right side.