



Photo 1 – Aerial view of accident helicopter at accident site. Photo provided by unknown.



Photo 2 – Accident helicopter at accident site. Photo provided by unknown.



Photo 3 – Accident helicopter's fenestron. Photo provided by unknown.



Photo 4 – Accident helicopter's ruptured fenestron blade root. Photo provided by unknown.