



Photo 1 – Accident airplane at accident site. Initial impact area and debris field in foreground. Photo provided by North Slope Borough Police Department.



Photo 2 – Left side view of accident airplane at accident site. Photo provided by North Slope Borough Police Department.



Photo 3 – Right side view of accident airplane at accident site. Photo provided by North Slope Borough Police Department.



Photo 4 – Accident airplane's propeller. Photo provided by North Slope Borough Police Department.