



Photo 1 – View of damaged main rotor blade (Photo courtesy of the Operator)



Photo 2 – View of left door track (Photo courtesy of the Operator)



Photo 3 – Damaged left sliding door (Photo courtesy of the Operator)



Photo 4 – Damaged left sliding door (Photo courtesy of the Operator)



Photo 5 – Left side of helicopter (Photo courtesy of the Operator)