



Photo 1 – N8875C Piper PA-22-135 at the accident scene. (Photograph courtesy of the Alaska State Troopers.)



Photo 2 - Right wing and fuselage damage. (Photograph courtesy of the Alaska State Troopers.)