

Carburetor Icing Probability Graph – ANC20LA099

Airplane: Cessna 170B

Engine: Franklin PZL 6A-350-C2

Fuel: Aviation Gas (AVGAS)

Accident Date: 09/22/2020

Accident Location: Big Lake, AK

Accident Time: 1900 Local

Celsius to Fahrenheit Conversion:

Temperature, 13° C = 55.4° F

Dew Point, 3° C = 37.4° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

