



Photo 1 – Picture of accident gyroplane, the cone indicates a mark where the rotor struck the ground (Photo courtesy of the FAA)



Photo 2 – View of the accident gyroplane while facing northeast (Photo courtesy of the FAA)



Photo 3 – View of the accident gyroplane displaced rotor blade (Photo courtesy of the FAA)