



Photo 1 – Exemplar picture of the accident airplane (Photo courtesy of the FAA)



Photo 2 – View of wreckage and impacted trees (Photo courtesy of the Clackamas County Sheriff's Office and Navy Rescue)



Photo 3 – Additional view of accident airplane (Photo courtesy of the Clackamas County Sheriff's Office and Navy Rescue)



Photo 4 - Additional view of accident airplane (Photo courtesy of the Clackamas County Sheriff's Office and Navy Rescue)