



Photo 1 – View of damaged wing (Photo courtesy of Airport Operations)



Photo 2 – View of damaged rudder (Photo courtesy of Alaska Claims Services, Inc.)