



Photo 1 – Accident airplane at accident site. Photo provided by the pilot.



Photo 2 – Accident airplane's substantially damaged left wing. Photo provided by pilot.