



Photo 1 – Rear view of damaged right wing and right elevator (Photo courtesy of the FAA)



Photo 2 – Front view of damaged right wing and right elevator (Photo courtesy of the FAA)



Photo 3 – Additional view of damaged elevator (Photo courtesy of the FAA)