



Photo 1 – View of accident airplane (Photo courtesy of the pilot)



Photo 2 – View of elevator damage (Photo courtesy of the pilot)



Photo 3 – View of bolt from rudder cable (Photo courtesy of the pilot)



Photo 4 – Additional view of bolt from rudder cable (Photo courtesy of the pilot)