



Photo 1 – Accident helicopter at accident site.



Photo 2 - Accident helicopter at accident site.



Photo 3 – The accident helicopter’s separated transmission and rotor head with the blades still attached.



Photo 4 – Accident helicopter's engine at the accident site.



Photo 5 – Accident helicopter's tail rotor at accident site.