



Photo 1 –Left side of accident airplane. Photo provided by the NTSB.



Photo 2 – Right side view of accident airplane. Photo provided by the NTSB.



Photo 3 – View of wire bundle over aft left tank fuel line in accident airplane. Photo provided by the NTSB.