



Photo 1 – Left side view of damaged airplane (Photo courtesy of Iliamna Air)



Photo 2 – Front view of airplane (Photo courtesy of Iliamna Air)



Photo 3 – Debris field from accident airplane (Photo courtesy of Iliamna Air)