



Photo 1 –Front left view of accident airplane wing after removal from accident site. Photo provided by the NTSB.



Photo 2 – Aft view of accident airplane after removal from accident site. Photo provided by the NTSB.



Photo 3 – Right side view of rudder on accident airplane after removal from accident site. Photo provided by the NTSB.