



Photo 1 –Front view of right-wing damage on accident airplane in owner’s hangar. Photo provided by owner.



Photo 2 – Aft view of right-wing damage on accident airplane in owner's hangar. Photo provided by owner.



Photo 3 – Front view of right-wing tip damage on accident airplane in owner’s hangar. Photo provided by owner.