



Photo 1 – Accident airplane at accident site. Photo provided by Kona Airport Fire Rescue.



Photo 2 – Accident airplane’s substantially damaged left wing. Photo provided by FAA.



Photo 3 – Accident airplane's emergency landing gear selector. Photo provided by FAA.



Photo 4 - Accident airplane's landing gear hydraulic power supply's reversible electric-motor with rotor removed. Photo provide by FAA.



Photo 5 – Accident airplane’s landing gear hydraulic power supply’s reversible electric-motor’s rotor. Photo provided by FAA.