



Photo 1 – Accident airplane at accident site. Photo provided by Alaska Seaplanes.



Photo 2 – The accident airplane’s substantially damage right wing and aileron. Photo provided by Alaska Seaplanes.