



Photo 1 –Right side view of accident airplane after recovery from accident site. Photo provided by the NTSB.



Photo 2 – . Left side view of accident airplane after recovery from accident site. Photo provided by the NTSB.



Photo 3 – Right side view wing strut damage of accident airplane after recovery from accident site. Photo provided by the NTSB.