



Photo 1 – Front of airplane (Courtesy of Alaska Wildlife Trooper)



Photo 2 – Damaged left wing strut (Courtesy of Alaska Wildlife Trooper)



Photo 3 – Damaged left elevator (Courtesy of Alaska Wildlife Trooper)