



Photo 1 –Right side view of accident airplane at accident site after recovery to shoreline. Photo provided by the NTSB.



Photo 2 – Left front underside view of the float on the accident airplane at accident site. Photo provided by NTSB.



Photo 3 – Right front underside view of the float on the accident airplane at accident site. Photo provided by NTSB.