

ANC23FA003

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of aircraft where it came to rest.



Photograph 2 - View of the cockpit and wing.



Photograph 3 - Google Earth image of the flight track.



Photograph 4 - View of engine and propeller.



Photograph 5 - View of engine and wing.