

ANC23FA056

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident site (Courtesy of the North Slope Borough Search and Rescue)



Photograph 2 - View of accident helicopter after recovery