



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Alaska Region

Photo Array

ANC23LA012



Photo 1 – View of airplane from the left rear where it came to rest. (Photo courtesy of the operator)



Photo 2 – View of airplane from the front right. (Photo courtesy of the operator)



Photo 3 – View of airplane from the empennage forward. (Photo courtesy of the operator)