



Photo 1 – Accident airplane after recovery, during engine examination. Photo provided by NTSB.



Photo 2 – Accident airplane’s wings after recovery, during engine examination. Photo provided by NTSB.