



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Alaska Region

Photo Array

ANC23LA016



Photo 1 – View of the front of the airplane where it came to rest (ANC Airport Police)



Photo 2 – View of the left side of the airplane (ANC Airport Police)



Photo 3 – View of right side of the airplane (ANC Airport Police)