



Photo 1 –Front view of accident airplane’s right-wing tip after recovery. Photo provided by Owner.



Photo 2 - Back view of accident airplane's right-wing tip after recovery. Photo provided by Owner.



Photo 3 - View of accident airplane's right-wing tip after recovery. Photo provided by Owner.