



Photo 1 – Accident helicopter at accident site. Photo provided by Anchorage Police and Fire.



Photo 2 – Left side of accident helicopter at recovery site. Photo provided by NTSB.



Photo 3 – View of accident helicopter’s tail boom at recovery site. Photo provided by NTSB.




Photo 4 – View of accident helicopter’s tail rotor assembly. Photo provided by NTSB.