



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Alaska Region

Photo Array

ANC23LA035



Photo 1 – View of airplane on the runway where it came to rest (Photo courtesy of ANC Police)



Photo 2 – View of the empennage of the airplane (Photo courtesy of ANC Police)