



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Alaska Region

Photo Array

ANC23LA036



Photo 1 – View of airplane where it came to rest (Photo courtesy of operator)



Photo 2 – View of the right side of the airplane (Photo courtesy operator)