



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Alaska Region

Photo Array

ANC23LA037



Photo 1 – View of the right side of the airplane where it came to rest (Photo courtesy of the Alaska State Troopers)



Photo 2 – View of the left side of the airplane where it came to rest (Photo courtesy of the Alaska State Troopers)



Photo 3 – View of the tail of the airplane (Photo courtesy of the Alaska State Troopers)