



Photo 1 – Left wing of accident airplane after recovery. Photo provided by owner.



Photo 2 – Right wing tip on accident airplane after recovery. Photo provided by owner.



Photo 3 – Right-wing leading-edge damage near landing light. Photo provided by owner.