



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Alaska Region

Photo Array

ANC23LA046



Photo 1 – View of airplane where it came to rest. (Photo courtesy of owner)



Photo 2 – View of airplane from the left after recovery. (Photo courtesy of FAA)



Photo 3 – View of the belly of the airplane after recovery. (Photo courtesy of FAA)