

ANC23LA048

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane amongst trees where it came to rest. (Courtesy of the pilot)



Photograph 2 - View of the airplane where it came to rest. (Courtesy of BLM)