

Carburetor Icing Probability Graph – ANC23LA062

Airplane: Cessna 180J

Engine: Lycoming O-470-R-50

Fuel: 100LL

Accident Date: 08/10/2023

Accident Location: Chaka Creek, AK

Accident Time: 1210 ADT

Weather: Pilot reported temperature 53° F; dew point 51° F

Source: Federal Aviation Administration
Special Airworthiness Information Bulletin CE-09-35
Carburetor Icing Prevention

