

ANC23LA087

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of wings, fuselage, and empennage (Courtesy of Pilot)



Photograph 2 - View of nose and bent wing strut (Courtesy of Pilot)



Photograph 3 - View of empennage (Courtesy of NTSB)



Photograph 4 - View of wings, fuselage, and vertical stabilizer (Courtesy of NTSB)