

ANC24FA092

INVESTIGATION PHOTOGRAPHS




**Photograph 1 - A screenshot from a video of the takeoff that shows the airplane on the runway.
(Courtesy of witness)**




Photograph 2 - View of the wreckage on fire after the accident.



Photograph 3 - View of the burned wreckage after recovery.



Photograph 4 View of a standard fuel hose (above) and the steel braided hose installed on the airplane (below).



Photograph 5 View of the kink in the steel braided hose from the carburetor to the gasoclator.