

ANC24LA003

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of right wing, fuselage, and empennage (Courtesy of Operator)



Photograph 2 - Image of right wingtip and right aileron (Courtesy of Operator)



Photograph 3 - Image of left wingtip (Courtesy of Operator)