

ANC24LA005

INVESTIGATION PHOTOGRAPHS



Photograph 1 –Front view of accident aircraft at accident site. (Courtesy of FAA)



Photograph 2 –Front right side view of accident aircraft at accident site. (Courtesy of FAA)



Photograph 3 –Left side view of accident aircraft at accident site. (Courtesy of FAA)