


ANC24LA006

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of vertical stabilizer and rudder (Courtesy of Pilot)



Photograph 2 - Image of internal fuselage (Courtesy of Pilot)