

ANC24LA007

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of the left wing viewed from the rear (Courtesy of FAA)



Photograph 2 - Image of the left wing root section viewed from the rear (Courtesy of Operator)



Photograph 3 - Image of the left wing viewed from the rear (Courtesy of Operator)



Photograph 4 - Image of the left wing viewed from the front (Courtesy of Operator)