

ANC24LA010


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of underside fuselage aft of nose strut (Courtesy of FAA)



Photograph 2 - Image of airplane on runway (Courtesy of FAA)



Photograph 3 - Image of firewall (Courtesy of FAA)