

Carburetor Icing Probability Graph – ANC24LA011

Airplane: Cessna 172P

Engine: Lycoming O-320-D2J

Fuel: Automotive

Accident Date: 12/23/2023

Accident Location: Kahului, HI

Accident Time: 1000 HAST

Weather: Observation facility (HOG) reported
temperature 77° F; dew point 66° F

Source: Federal Aviation Administration
Special Airworthiness Information Bulletin CE-09-35
Carburetor Icing Prevention

