


ANC24LA012

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Picture of the accident helicopter at the accident site. Courtesy of FAA**



**Photograph 2 - Picture of the fencing that the helicopter's landing gear skid got caught in.  
Courtesy of FAA**