

ANC24LA014

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of fuselage, empennage, and wings (Courtesy of Pilot)



Photograph 2 - Aerial view of crash site (Courtesy of Pilot)



Photograph 3 - Image of outboard left wing leading edge (Courtesy of Pilot)