

ANC24LA023

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Side View of Airplane (Courtesy of Owner)



Photograph 2 - View from Back of Airplane (Courtesy of Owner)



Photograph 3 - View From Front of Airplane (Courtesy of Owner)



Photograph 4 - Left Rear View of Airplane (Courtesy of Owner)



Photograph 5 - Impact Marks (Courtesy of Owner)