

ANC24LA024


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front of Aircraft (Courtesy of Owner)



Photograph 2 - Bottom View of Aircraft (Courtesy of Owner)



Photograph 3 - View of impact marks on runway (Courtesy of Owner)