

ANC24LA030

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of left wing and fuselage (Courtesy of Operator)



Photograph 2 - Image of detached left main landing gear (Courtesy of Operator)



Photograph 3 - Image of left wing, fuselage, and empennage (Courtesy of Operator)