

ANC24LA031

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Rear view of accident airplane (Courtesy of PAMR)



Photograph 2 - Right side of accident airplane (Courtesy of PAMR)



Photograph 3 - Front view of accident airplane (Courtesy of PAMR)



Photograph 4 - Marks from airplane propeller on runway (Courtesy of PAMR)